

## County Surveyor's Record, Douglas County, Oregon

East Bdy. of T. 21 S., R. 6 W.

CHAINS

Fir, 26 ins. dia., bears S.15°W., 21 lks. dist.,  
marked T 21 S R 6 W S 25 B T.

North on East boundary between secs. 19 & 24, on blank  
line; at 40.25 chs. to qr. sec. cor. standing, and at  
80.35 to place where old cor. to secs. 13, 24, 18 & 19  
stood; the stumps of some of the witness trees found.  
Reestablished this corner by setting post, 6 ins. dia.,  
4 ft. long in ground with marked stone, 12 ins., marked  
T 21 S S 18 on NE., R. 5 W S 19 on SE., R 6 W S 24 on  
SW., S 13 on NW. face, with 3 notches on N. & S. edges;  
from which

Cedar, 27 ins. dia., bears N.40°W., 75 lks. dist.,  
marked T 21 S R 6 W S 13 B T.

Cedar, 14 ins. dia., bears S.60°W., 50 lks. dist.,  
marked T 21 S R 6 W S 24 B T.

Maple, 12 ins. dia., bears S.42°E., 27 lks. dist.,  
marked T 21 S R 5 W S 19 B T.

Hemlock, 8 ins. dia., bears N.10°E., 45 lks. dist.,  
marked T 21 S R 5 W S 18 B T.

North on East boundary between secs. 13 & 18.

Va. 20 $\frac{1}{2}$ °E.

Descend slope 11°.

12.00 Slope 12°.

19.00 Branch, 1 lk. wide, flows West; ascend 29°.

27.00 Slope 46°.

32.00 Slope 21°.

35.00 Top of spur; descend 13°.

40.00 Old  $\frac{1}{4}$  cor. gone. Set a post, 4 ins. dia., 4 ft. long,  
with marked stone, 12 ins. in ground, marked  $\frac{1}{4}$  S on  
W. face; from which

Fir, 20 ins. dia., bears S.19°E., 47 lks. dist.,  
marked  $\frac{1}{4}$  S B T.

Fir, 24 ins. dia., bears S.17°W., 34 lks. dist.,  
marked  $\frac{1}{4}$  S B T.