

## South Bay. of T. 21 S., R. 6 W.

CHAINS

stone, 12 ins. in ground, marked  $\frac{1}{2}$  S on N. face; from which

Fir, 24 ins. dia., bears S.27°E., 20 lks. dist., marked  $\frac{1}{2}$  S B T.

Fir, 30 ins. dia., bears N.47°W., 23 lks. dist., marked  $\frac{1}{2}$  S B T.

53.50 Ascend slope 27°.

64.20 Cross ridge; descend 25°.

80.10 To place where cor. to secs. 31, 32, 5 & 6 stood. Post gone and 3 of bearing trees standing. Re-established the cor. by setting post, 6 ins. dia., 4 ft. long, with marked stone, 12 ins. in ground, marked T 21 S S 32 on NE., R 6 W S 5 on SE., T 22 S S 6 on SW., S 31 on NW. face, with 5 notches on E. and 1 on West edges; from which

Fir, 70 ins. dia., bears N.56°E., 19 lks. dist., marked T 21 S R 6 W S 32 B T.

Fir, 36 ins. dia., bears N.30°W., 22 lks. dist., marked T 21 S R 6 W S 31 B T.

Hemlock, 24 ins. dia., bears S.33°E., 50 lks. dist., marked T 22 S R 6 W S 5 B T.

Cedar, 24 ins. dia., bears S.4°W., 42 lks. dist., marked T 22 S R 6 W S 6 B T.

---

West on South boundary bet. secs. 31 & 6.

V.21°E.

On blank line.

77.50 The cor. to township.

Survey ended Sept. 28th, 1884.

---

Subdivisions of T. 21 S., R. 6 W.  
Survey by Wm. P. Wright under Contract No. 514 dated  
August 27th, 1884.

Survey commenced September 28, 1884.

Start from the cor. to secs. 23, 24, 25 and 26, which is a post, 4 ins. dia., 4 ft. long, marked T 21 S S 24 on