

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 21 S., R. 6 W.

CHAINS

1, 2, 11 & 12.

Thence. I run

S.89°47' West, on true line, between secs. 2 & 11.

Descend slope 11°.

- 8.50 Branch, 3 lks. wide, flows NW.; ascend 10°.
- 12.50 Descend 12°.
- 15.75 Branch, 3 lks. wide, flows N.; ascend 20°.
- 31.50 Descend 30°.
- 40.00 Set post, 4 ins. dia., 4 ft. long, with marked stone, 12 ins. in ground, for qr. sec. cor., marked $\frac{1}{4}$ S on N. face; from which
- Cedar, 16 ins. dia., bears N.72°W., 30 lks. dist., marked $\frac{1}{4}$ S B T.
- Hemlock, 20 ins. dia., bears S.50°E., 16 lks. dist., marked $\frac{1}{4}$ S B T.
- 46.00 Branch, 6 lks., flows NE.; ascend 15°.
- 48.50 Descend 24°.
- 57.00 Branch, 2 lks. wide, flows S.; ascend 12°.
- 68.50 Along flat.
- 80.00 The cor. to secs. 2, 3, 10 & 11.

North, on true line, between secs. 2 & 3.

V.20 $\frac{1}{2}$ °E.

Ascend 20°.

- 22.50 Top of ridge, E. & W.; descend 25°.
- 40.00 Set post, 4 ins. dia., 4 ft. long, with marked stone, 12 ins. in ground, for qr. sec. cor., marked $\frac{1}{4}$ S on W. face; from which
- Fir, 24 ins. dia., bears S.55°E., 16 lks. dist., marked $\frac{1}{4}$ S B T.
- Fir, 20 ins. dia., bears S.67°W., 14 lks. dist., marked $\frac{1}{4}$ S B T.
- 83.70 Intersect North boundary of Town., 354 lks. East of cor. to secs. 34 & 35. Found post much decayed.
- Set post, 6 ins. dia., 4 ft. long, with marked stone, 12