

## County Surveyor's Record, Douglas County, Oregon

## Subdivisions of T. 21 S., R. 6 W.

## CHAINS

- 40.00 Set post, 4 ins. dia., 4 ft. long, 12 ins. in ground, with marked stone, marked  $\frac{1}{4}$  S on W. face; from which Cedar, 14 ins. dia., bears N.44°W., 55 lks. dist., marked  $\frac{1}{4}$  S B T.
- Cedar* Fir, 8 ins. dia., bears N.69°E., 48 lks. dist.,  
*W.N.H. #239* marked  $\frac{1}{4}$  S B T.
- 57.00 Branch, 3 lks. wide, flows West; ascend 30°.
- 80.00 Set post, 6 ins. dia., 4 ft. long, with marked stone, 12 ins. in ground, for cor. to secs. 3, 4, 9 & 10, marked T 21 S S 3 on NE., R 6 W S 10 on SE., S 9 on SW., S 4 on NW. face, with 5 notches on S. & 3 on E. edges; from which
- Fir, 5 ins. dia., bears N.10°E., 51 lks. dist., marked T 21 S R 6 W S 3 B T.
- Willow, 3 ins. dia., bears S.19°E., 12 lks. dist., marked T 21 S R 6 W S 10 B T.
- Oak, 3 ins. dia., bears S.51°W., 9 lks. dist., marked T 21 S R 6 W S 9 B T.
- Balm, 3 ins. dia., bears N.17°W., 49 lks. dist., marked T 21 S R 6 W S 4 B T.
- 
- East, on random line, between secs. 3 & 10.  
V.21°E.
- 40.00 Set temp. qr. sec. cor.
- 80.20 Intersect N. & S. line, 42 lks. South of cor. to secs. 2, 3, 10 & 11.  
Thence I run  
S.89°42'West, on true line, bet. secs. 3 & 10.  
Ascend slope 20°.
- 15.00 32°
- 20.50 Cross ridge, N. & S.; descend 35°.
- 37.50 Branch, 2 lks. wide, flows NW.; ascend 34°.
- 40.10 Set post, 4 ins. dia., 4 ft. long, with marked stone, 12 ins. in ground, for qr. sec. cor., marked  $\frac{1}{4}$  S on N. face; from which