

Subdivisions of T. 21 S., R. 5 W., W. M.

CHAINS		
46.35	Stream, 6 lks. wide, course SE.	-50
79.00	Sec. cor. Land, mountainous; soil, 3rd rate. Timber, Fir; undergrowth, Vine maple. The remainder of this township is steep, rocky and unfit for cultivation and its survey is omitted.	+200
GENERAL DESCRIPTION		
<p>The surveyed portion of this township is mostly hilly or mountainous; the creek bottoms, however, afford some good farming situations. The timber is scattering Fir, and Oak. The principal road between the Willamette and Umpqua settlements passes through the SE. part of the township.</p>		
<p>Subdivisions lines of T. 21 S., R. 5 W., W. M. as surveyed by W. H. Byar, Deputy Surveyor, under Contract No152, dated June 3, 1871.</p>		
<p>The cor. and witness trees to sec. 19, 20, 29 and 30, being destroyed. Begin at $\frac{1}{2}$ sec. post bet. secs. 29 and 30.</p> <p style="text-align: right;">Va.20*E.</p>		
5.00	Enter burn.	
20.00	Top of ridge, Course SE.	+200
40.00	Set post cor. to secs. 19, 20, 29 and 30, from which A Fir, stub, 24 ins. dia., bears N.15*E., 82 lks. dis. A Fir stub, 30 ins. dia., bears S.63*E., 150 lks. dis. A Fir stub, 30 ins. dia., bears S.38*W., 48 lks. dis. A Fir stub, 36 ins. dia., bears N.18*W., 70 lks. dis. Land, 1st and 2nd rate. No timber.	