

7

North Boundary of T. 22 S., R. 8 W.
 As Surveyed By W.H. Byars, U.S., Deputy Surveyor, under Contract No. 376
 Dated January 22, 1881

CHAINS	
	<p>A Hemlock Tree, 16 ins. diam., bears N.55*E., 78 links.</p> <p>A Hemlock Tree, 8 ins. diam., bears N.72*W., 22 links.</p> <p>Land Mountainous and broken.</p>
	<hr/> <p>Running West on South Boundary of Section 33</p> <p style="text-align: right;">Va. 18* E.</p>
26.00	2 links wide, course NE.
35.00	Top of Ridge, course SE.
40.00	Set Fir Post, for $\frac{1}{4}$ sec. cor. from which:
	A Fir Tree, 20 ins. diam., bears N.80*W., 240 lks.
	A Fir Tree, 20 ins. diam., bears S.85*W., 187 lks.
60.20	Creek 2 links wide, course S.
65.60	Creek 2 links wide, course S.
80.00	Set Maple post for section corner to sec. 33 & 32 from which:
	A Alder Tree, 8 ins. diam., bears N.52*E., 42 lks.
	A Alder Tree, 8 ins. diam., bears N.58*W., 69 lks.
	Land Mountainous and broken land 3rd. rate.
	<hr/> <p>Running West on South boundary of section 32</p> <p style="text-align: right;">Va. 19* E.</p>
35.00	Top of Spur, course South
40.00	Set Fir Post, for $\frac{1}{4}$ sec. corner from which:
	A Fir Tree, bears N.41*E., 60 lks., 30 ins. diam.
	A Fir Tree, bears S.80*E., 50 lks., 24 ins. diam.
84.00	Creek 4 links wide C. N.
99.36	To Section Corner.
	Land Mountainous 2nd. rate heavily timbered, chiefly Fir and Cedar.
	February 23, 1881