

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 21 S., R. 8 W.

As Surveyed By Wm. P. Wright, Deputy Surveyor, under Contract No. 486
Dated August 1, 1883

CHAINS

I commence at the corner to section 35 and 36 on the South boundary of township which is a post 4 ins. diam. in ground, marked T 21 S, S 36 on NE, R 8 W on SE, T 22 S on SW, S 35 on NW faces with one notch on E and 5 on W edges from which:

Fir, 36 ins. diam., bears N.70*W., 10 lks. dist.,

Marked T 21 S R 8 W S 35 B T

Fir, 36 ins. diam., bears N.20*E., 20 lks. dist.,

Marked T 21 S R 8 W S 36 B T

Thence I run

North, between secs. 35 & 36

Va. 20 $\frac{1}{2}$ * E.

Descend Mountain

40.00 Fir, 50 ins. diam., for $\frac{1}{4}$ sec. corner marked $\frac{1}{4}$ S on W faces from which:

Hemlock, 18 ins. diam., bears W. 33 lks.,

Marked $\frac{1}{4}$ S B T

Hemlock, 24 ins. diam., bears E. 50 lks.,

Marked $\frac{1}{4}$ S B T

57.00 Cross Creek 20 lks. wide flows W. Ascend

80.00 Set post 6 ins. diam., 4 ft. long with marked stone 12 ins. in ground for corner to section 25, 26, 35 & 36, marked T 21 S, S 25 on NE, R 8 W, S 36 on SE, S 35 on SW, S 26 on NW face with one notch on E & S edge from which:

Fir, 18 ins. diam., N.76*W., 36 lks. dist.,

Marked T 21 S R 8 W S 26 B T

Fir, 12 ins. diam., S.14*W., 33 lks. dist.,

Marked T 21 S R 8 W S 35 B T

Fir, 6 ins. diam., S.70*E., 40 lks. dist.,

Marked T 21 S R 8 W S 36 B T

Fir, 18 ins. diam., N.70*E., 61 lks. dist.,

Marked T 21 S R 8 W S 25 B T

Land rough, soil poor, 3rd. rate,