

Subdivisions of T. 21 S., R. 8 W.

CHAINS

Timber, Fir and Hemlock

Thick undergrowth of Thimbleberry and Sallal-80 chs.

East, on Random line between secs. 25 & 36

Va. $20\frac{1}{2}$ * E.

40.00 Set Temp. $\frac{1}{4}$ section corner

80.50 Intersect East boundary of town 50 lks. North of cor. to sec. 25, 36, 30 & 31 which is a post 4 ins. in ground marked T 21 S, S 30 on NE, R 7 W, S 31 on SE, R 8 W, S 36 on SW, S 25 on NW face with one notch on S, 5 on N edge from which:

Fir, 7 ins. diam., bear N.77*E., 17 lks. dist.,

Marked T 21 S R 7 W S 30 B T

Fir, 7 ins. diam., bears S.57*E., 9 lks. dist.,

Marked T 21 S R 7 W S 31 B T

Fir, 4 ins. diam., bears S.13*W., 200 lks. dist.,

Marked T 21 S R 8 W S 36 B T

Fir, 24 ins. diam., bears N.25*W., 73 lks. dist.,

Marked T 21 S R 8 W S 25 B T

Thence I run on true line N.89*W., between secs. 25 & 36

Ascend

4.00 Descend

37.00 Branch 10 lks. wide flows S, ascend

40.25 Maple, 20 ins. diam., for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S on N face from which:

Maple, 18 ins. diam., bears N.25*E., 10 lks. dist.,

Marked $\frac{1}{4}$ S B T

Chinquapin, 12 ins. diam., bears S.12*W., 47 lks.

dist., Marked $\frac{1}{4}$ S B T

80.50 The cor. to secs. 25, 26, 35 & 36

Land rough, soil, poor and stony

Timber, Fir and Hemlock

Thick undergrowth of Sallal, 80.50 chs.

September 8, 1883