

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 21 S., R. 8 W.

CHAINS

Dogwood, 6 ins. diam., bears S.9*W., 25 lks. dist.,

Marked T 21 S R 8 W S 24 B T

Fir, 6 ins. diam., bears N.60*W., 24 lks. dist.,

Marked T 21 S R 8 W S 13 B T

Thence I run

North 89*30' W., on true line between secs. 13 & 24

20.00 Descend Mountain

40.23 Set post 4 ins. diam., 4 ft. long with marked stone 12 ins. in ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S on N face from which:

Cedar, 18 ins. diam., bears S.18*W., 42 lks. dist.,

Marked $\frac{1}{4}$ S B T

Fir, 12 ins. diam., bears N.50*E., 14 lks. dist.,

Marked $\frac{1}{4}$ S B T

80.47 The cor. to secs. 13, 14, 23, & 24

Land Mountainous, steep and rocky

Not much soil.

Timber, poor Fir

Thick undergrowth of Sallal and Thimbleberry, 80.47 chs.

North, between secs. 13 & 14

Va. 19*45' E.

Ascend Mountain

23.00 Descend

40.00 Fir, 14 ins. diam., for $\frac{1}{4}$ sec. cor. marked stone $\frac{1}{4}$ S on W face from which:

Fir, 20 ins. diam., bears N.80*E., 27 lks. dist.,

Marked $\frac{1}{4}$ S B T

Fir, 6 ins. diam., bears N.70*W., 20 lks. dist.,

MARKED $\frac{1}{4}$ S B T

47.00 Descend Mountain along East Slope.

80.00 Set post 6 ins. diam., 4 ft. long with marked stone 12 ins. in ground for cor. to secs. 11, 12, 13 & 14, marked T 21 S, S 12 on NE, R 8 W, S 13 on SE, S 14 on SW, S 11 on NW face with one notch on E and 4 on S edge from which: