

Subdivisions of T. 21 S., R. 8 W.

CHAINS	<p>Fir, 5 ins. diam., bears N.85*W., 10 lks. dist., Marked $\frac{1}{4}$ S B T</p> <p>Fir, 5 ins. diam., bears S.85*W., 12 lks. dist., Marked $\frac{1}{4}$ S B T</p>
80.20	<p>The cor. to secs. 27, 28, 33 & 34</p> <p>Land rough and steep</p> <p>Soil poor, thin, full of rocks</p> <p>Timber, Fir and Cedar of poor quality</p> <p>Thick undergrowth of Sallal--80.20 chs.</p> <p style="text-align: right;">September 17, 1883</p>
	<p>North, between secs. 27 & 28</p> <p style="text-align: right;">Va. 20* E.</p>
	<p>Descend</p>
7.00	<p>Ascend</p>
10.00	<p>Descend</p>
40.00	<p>Set post 4 ins. diam., 4 ft. long with marked stone 12 ins. in ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S on W face from which:</p> <p style="padding-left: 40px;">Willow, 3 ins. diam., bears N.80*E., 18 lks. dist., Marked $\frac{1}{4}$ S B T</p> <p style="padding-left: 40px;">Fir, 70 ins. diam., bears S.30*W., 40 lks. dist., Marked $\frac{1}{4}$ S B T</p>
80.00	<p>Fir, 10 ins. diam., for cor. to secs. 21, 22, 27 & 28 marked T 21 S, S 22 on NE, R 8 W, S 27 on SE, S 28 on SW, S 21 on NW, face with 3 notches on E and 2 on S edge from which:</p> <p style="padding-left: 40px;">Fir, 25 ins. diam., bears N.37*E., 26 lks. dist., Marked T 21 S R 8 W S 22 B T</p> <p style="padding-left: 40px;">Fir, 30 ins. diam., bears N.10*W., 26 lks. dist., Marked T 21 S R 8 W S 21 B T</p> <p style="padding-left: 40px;">Fir, 10 ins. diam., bears S.27*W., 18 lks. dist., Marked T 21 S R 8 W S 28 B T</p> <p style="padding-left: 40px;">Fir, 10 ins. diam., bears S.45*E., 39 lks. dist., Marked T 21 S R 8 W S 27 B T</p>
	<p>Land Mountainous</p> <p>Soil, poor, thin, full of rocks</p>