

27

Subdivisions of T. 21 S., R. 8 W.

CHAINS

NW, face with 5 notches on S & 3 on E edge from which:
 Fir, 10 ins. diam., bears N.38*E., 21 lks. dist.,
 Marked T 21 S R 8 W S 3 B T
 Fir, 8 ins. diam., bears S.64*E., 41 lks. dist.,
 Marked T 21 S R 8 W S 10 B T
 Fir, 10 ins. diam., bears S.72*W., 40 lks. dist.,
 Marked T 21 S R 8 W S 9 B T
 Fir, 10 ins. diam., bears N.77*W., 16 lks. dist.,
 Marked T 21 S R 8 W S 4 B T

Land Mountainous
 Land on River good, level
 Soil, first rate
 Timber Fir and Maple
 Thick undergrowth of young Fir--80 chs.

September 19, 1883

East, on Random line between secs. 3 & 10
 Va. 20* E.
 40.00 Set Temp. $\frac{1}{4}$ sec. cor.
 79.60 Intersect N & S line, 50 lks. S of cor. to secs. 2, 3,
 10 & 11, Thence
 S.89*39*W., on true line between secs. 3 & 10
 Along foot-hill
 19.25 Cross Smith River course NW, 100 lks. wide along bottom
 39.80 Set post 4 ins. diam., 4 ft. long with marked stone 12
 ins. in ground for $\frac{1}{4}$ sec. cor., Marked $\frac{1}{4}$ S on N face
 from which:
 Fir, 7 ins. diam., bears S.14*W., 4 lks. dist.,
 Marked $\frac{1}{4}$ S B T
 Fir, 5 ins. diam., bears N.33*E., 4 $\frac{1}{2}$ lks. dist.,
 Marked $\frac{1}{4}$ S B T
 Along Ridge
 79.60 The cor. to secs. 3, 4, 9 & 10
 Land ^{not} very rough
 Soil on Smith River, bottom good
 Timber, scattering Fir