

County Surveyor's Record, Douglas County, Oregon

40

Subdivisions of T. 21 S., R. 8 W.

CHAINS

Soil, none at all first 30 chs., balance 3rd. rate

Timber, Fir, good quality

Thick undergrowth of Sallal--80.10 chs.

West, on Random line between secs. 30 & 31

Va. 20* E.

40.00 Set Temp. $\frac{1}{4}$ sec. cor.

99.75 Intersect West bound of town, 18 lks. N of cor. to secs. 25, 30, 30 & 31 which is a fir 4 ins. diam., marked T 21 S, S 30 on NE, R 8 W, S 31 on SE, R 9 W, S 36 on SW, S 25 on NW face with 5 notches on N & 1 on S edge from which:

Fir, 12 ins. diam., bears N.55*E., 7 lks. dist.,

Marked T 21 S R 8 W S 30 B T

Fir, 12 ins. diam., bears S.28*E., 16 lks. dist.,

Marked T 21 S R 8 W S 31 B T

Fir, 5 ins. diam., bears N.57*W., 5 lks. dist.,

Marked T 21 S R 8 W S 25 B T

Fir, 6 ins. diam., bears S.36*W., 16 lks. dist.,

Marked T 21 S R 9 W S 36 B T

Thence

S.89*54'E., on true line between secs. 30 & 31

25.00 Cross Creek 15 lks. wide flows SW-Ascend

59.75 Set post 4 ins. diam., 4 ft. long with marked stone 12 ins. in ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S on N face from which:

Fir, 10 ins. diam., bears S.40*E., 10 lks. dist.,

Marked $\frac{1}{4}$ S B T

Fir, 10 ins. diam., bears N.38*W., 19 lks. dist.,

Marked $\frac{1}{4}$ S B T

99.75 The cor. to secs. 29, 30, 31 & 32

Land mostly mountain top

Rolling Soil, 3rd. rate

Timber, good quality Fir and Cedar

Thick undergrowth of Hazel and Sallal--99.85 chs.

September 25, 1883