

County Surveyor's ²Record, Douglas County, Oregon

Subdivisions of T. 21 S., R. 9 W. W. M.

CHAINS 15.43	<p>Marked an alder, 12 ins. diam., standing in bottom of canon, course N.; very steep broken mountains further East.</p> <p style="text-align: right;">June 18, 1877.</p>	
<p>Subdivisions of T. 21 S., R. 9 W., W. M., as surveyed by F. M. Johnson, Deputy Surveyor, under contract no. 314, dated Dec. 27, 1878.</p>		
	<p>Beginning at the NE cor. of sec. 5 and running on the E. line of sec. 5.</p> <p style="text-align: right;">va. 19*30'</p>	
7.00	South along side hill sloping W. through heavy timber to top of ridge. Thence	
20.00	To bed of Buck creek, course NW. Thence	-320
30.00	To top of rocky spur, thence	+375
36.00	Along rocky side hill to top of ridge course NW, thence down side hill sloping South, with timber along the whole line, and at	
40.00	<p>Set $\frac{1}{2}$ sec. post from which</p> <p style="padding-left: 40px;">A hemlock, 26 ins. diam., bears S.76*W., 16 lks. dist.</p> <p style="padding-left: 40px;">A maple, 16 ins. diam., bears S.71*E., 74 lks. dist.</p> <p>Thence over very rough and heavy timbered land, crossing several deep ravines and sharp ridges on the line and at</p>	
80.00	<p>Set rock 40 x 14 x 24 ins. for cor. to secs. 4, 5, 8 and 9, from which</p> <p style="padding-left: 40px;">A fir, 44 ins. diam., bears N.47*E., 107 lks. dist.</p> <p style="padding-left: 40px;">A fir, 40 ins. diam., bears S.41*E., 124 lks. dist.</p> <p style="padding-left: 40px;">A fir, 24 ins. diam., bears S.83*W., 66 lks. dist.</p> <p style="padding-left: 40px;">A fir, 48 ins. diam., bears N.43*W., 135 lks. dist.</p> <p style="text-align: right;">Va. 19*30'.</p>	
64.43	<p>West, on random line bet. secs. 5 and 8, at intersect marked alder at end of former survey 23 lks. S. Thence returning on true line South 89*48'E.</p>	