

Sub-divisions of T. 21 S., R. 9 W., W. M.

CHAINS	Va. 19*30'	
	Over rocky ridges covered with burnt timber and some under-brush, and at	
24.50	Set $\frac{1}{4}$ Section Post, from which A Fir, 30 ins. diam., bears S.30*W., 50 lks. dist. A Maple, 12 ins. diam. bears N.37*E. 71 lks. dist.	
	Thence over bench land covered with under-brush and some burnt timber.	
39.50	To Spring branch, course NW. Thence over rocky and uneven lands, under-brush and some burnt timber.	
54.50	Rocky Canyon, thence rising steep hill from canyon.	+270
64.43	To intersect corner to 4, 5, 8 and 9.	
West Boundary of T.21 S., R. 8 W., W. M. As surveyed by William P. Wright, Deputy Surveyor, under Contract No. 486, August 1, 1883.		
Begin at the Corner to Townships 21 and 22 S., Rs. 8 and 9 West, which is a post 4 ins. square, marked, T 21 S R 8 W S 31 on NE. face, T 22 S R 8 W S 6 on SE. face, T 22 S R 9 W S 1 on SW. face and T 21 S R 9 WS 36 on NW. face, with 6 notches on each edge, from which A Fir, 30 ins. diam., bears N.35*E., 52 lks. dist., marked T 21 S R 8 W S 31 B T A Fir, 24 ins. diam., bears S.25*E., 28 lks. dist., marked T 22 S R 8 W S 6 B T A Fir, 16 ins. diam., bears S.15*W., 36 lks. dist., marked T 22 S R 9 W S 1 B T A Fir, 16 ins. diam., bears N.75*W., 50 lks. dist., marked T 21 S R 9 W S 36 B T Thence I run North between Secs. 31 and 36. Descend Mountain. Va. 19* E.		
37.50	Cross Creek 25 lks. wide, flows West. Ascend.	
40.00	Set post 4 ins. diam., 4 feet long with marked stone 12 ins. in ground, for $\frac{1}{4}$ Sec. Cor., marked $\frac{1}{4}$ Section on W. face, from which A Cedar, 36 ins. diam., bears West 21 lks. dist., marked $\frac{1}{4}$ S B T A Cedar, 15 ins. diam., bears S.35*E., 23 lks. dist. marked $\frac{1}{4}$ S B T	