

County Surveyor's Record, Douglas County, Oregon.

Resurvey of the West Boundary of T. 21 S., R. 8 W.

<p>CHAINS 36.31</p>	<p>The cor. to secs. 6 and 7.</p> <p>Whole length of line 71.50 chs.</p>	
	<p>The South Boundary of T. 21 S., R. 9 W. same deputy and contract.</p>	
	<p>I commenced at cor. to Tps. 21 and 22 S Rgs 8 and 9 W which I established as follows,</p> <p>Set fir post, 4 ft. long, 4 ins.sq., 24 ins. in the ground marked T 21 S S 31 on the NE, R 8 W S 6 on the SE, T 22 S S 1 on the SW, and R 9 W S 36 on the NW faces with 6 notches on the N, E, S and W edges, from which</p> <p style="padding-left: 40px;">A fir, 24 ins. diam., bears S.25*E., 28 lks.dist. marked T 22 S R 8 W S 6 B T.</p> <p style="padding-left: 40px;">A fir, 20 ins. diam., bears S.15*W., 36 lks.dist. marked T 22 S R 9 W S 1 B T.</p> <p>The stumps of the bearing trees in secs. 31 and 36 were standing, and all agreeing with notes furnished me by the U. S. Surveyor General. I marked</p> <p style="padding-left: 40px;">A fir, 8 ins. diam., bears N.69*E., 22 lks. dist. marked T 21 S R 8 W S 31 B T.</p> <p style="padding-left: 40px;">A fir, 6 ins. diam., bears N.78*W., 27 lks. dist. marked T 21 S R 9 W S 36 B T.</p> <p>Note: Owing to the heavy timber and dense undergrowth I could not take observations at this corner.</p> <p>Thence I run</p> <p>West on South Boundary of sec. 36,</p> <p style="text-align: right;">Va.20*E.</p> <p>Through dense brush and timber along hill side, sloping NE.</p>	
<p>7.70</p>	<p>Creek, 1 lk. wide, course N.</p> <p>Pass over spur.</p>	<p>-150</p>
<p>14.50</p>	<p>Creek, 1 lk. wide, course NE.</p> <p>Ascend</p>	
<p>35.00</p>	<p>Top of rocky ridge course NE and SW</p>	<p>+350</p>