

County Surveyor's Record, ^{12.}Douglas County, Oregon

The South Boundary of T. 21 S., R. 9 W.

CHAINS		
14.25	Creek, 2 lks. wide, course SW. Ascend,	-100
17.00	Top of ridge sloping SW Descend	+50
39.00	Patterson Creek, 80 lks. wide, course S.	-600
40.00	Set sandstone 24 x 18 x 3 ins., 18 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S on the N. face with small mound of stone around corner, from which An alder, 6 ins. diam., bears N.28*W., 59 lks. dist. marked $\frac{1}{4}$ S B T. A hemlock, 30 ins. diam. bears S.38*E., 138 lks. dist. marked $\frac{1}{4}$ S B T. Ascend	
62.50	Top of ridge course NW and SE Pass over cone	+700
69.50	Same ridge, course NE and SW Descend	
80.00	Set hemlock post 4 $\frac{1}{2}$ ft. long, 4 ins. sq., 24 ins. in the ground for cor. to secs. 34, 35, 2 and 3 marked T 21 S S 35 on the NE, R 9 W S 2 on the SE, T 22 S S 3 on the SW and S 34 on the NW faces with 2 notches on the E and 4 notches on the W. edges, from which A cedar, 7 ins. diam., bears N.53*15'E., 6 lks. dist., marked T 21 S R 9 W S 35 B T. A cedar, 30 ins. diam. bears S.80*30'E., 41 lks. dist. marked T 22 S R 9 W S 2 B T. A hemlock, 26 ins. diam. bears S.53*W., 85 lks. dist., marked T 22 S R 9 W S 3 B T. A hemlock, 10 ins. diam. bears N.79*W., 23 lks. dist., marked T 21 S R 9 W S 34 B T. Land, broken and mountainous. 80.00 chs. Soil, 2nd and 3rd rate. Heavily timbered with fir, hemlock and cedar 80.00 chs.	