

Subdivisions of T. 21 S., R. 9 W.

CHAINS

Set fir post, 5 ft. long, 5 ins. sq., 24 ins. in the ground on hill side sloping W., marked T 21 S S 30 on the NE, R 8 W S 31 on the SE, R 9 W S 36 on the SW, and S 25 on the NW faces with 1 notch on the S. and 5 notches on the N. edges, from which

A fir, 12 ins. diam., bears N.53°E., 63 lks. dist. marked T 21 S R 8 W S 30 B T.

A fir, 48 ins. diam., bears S.44°E., 88 lks. dist. marked T 21 S R 8 W S 31 B T.

A fir, 36 ins. diam., bears S.15°W., 111 lks. dist., marked T 21 S R 9 W S 36 B T.

A fir, 12 ins. diam., bears N.72°W., 143 lks. dist., marked T 21 S R 9 W S 25 B T.

Note: The B T's of the original survey had been destroyed, only the stumps standing and agreeing with notes furnished me by the U. S. Sur. General.

Thence I run

S.89°50'W. on true line, bet. secs. 25 and 36.

Va.19°30'E.

Descend

5.00 Creek, 1 lk. wide, course S.

Pass over spur.

10.80 Creek, 1 lk. wide, course S.

Ascend

16.00 Top of ridge, course N. and S.

Descend

40.31 Set hemlock post, 4½ ft. long, 4 ins. sq., 24 ins. in the ground in canyon for ¼ sec. cor. marked ¼ S on the N. face, from which

A maple, 16 ins. diam., bears S.42°E., 35 lks. dist., marked ¼ S B T.

A cedar, 14 ins. diam., bears N.44°W., 61 lks. dist., marked ¼ S B T.

+50