

County Surveyor's ⁴⁸Record, Douglas County, Oregon

Subdivisions of T. 21 S., R. 9 W.

CHAINS 40.16	<p>Set sandstone 12 x 12 x 6 ins., 9 ins. in ground on steep hill side sloping E. for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S on the N. face, from which</p> <p style="padding-left: 40px;">A cedar, 20 ins. diam., bears N.82*E., 114 lks. dist. marked $\frac{1}{4}$ S B T.</p> <p style="padding-left: 40px;">A cedar, 20 ins. diam., bears S.2*E., 43 lks. dist., marked $\frac{1}{4}$ S B T.</p> <p>Ascend</p>	
46.50	<p>Top of ridge sloping N.</p> <p>Descend</p>	+75
52.50	<p>Dry bed of stream, 4 lks. wide, course N.</p> <p>Ascend</p>	-100
74.00	<p>Top of ridge, course N and S</p> <p>Descend</p>	+150
80.31	<p>The cor. to secs. 22, 23, 26 and 27</p> <p>Land, mountainous and broken 80.31 chs.</p> <p>Soil, 2nd and 3rd rate.</p> <p>Heavily timbered with fir, hemlock and cedar 80.31 chs.</p> <p>Dense undergrowth of vine maple, hazel, salal-berry, rhododendron and arrow-wood 80.31 chs.</p> <p style="text-align: right;">September 10, 1894.</p>	-125?
<p>North, 00*02'W. bet secs. 22 and 23</p> <p style="text-align: right;">Va.20*E.</p>		
14.75	<p>Ascend along hill side sloping SW</p> <p>Top of ridge sloping NW</p> <p>Descend along hill side sloping NE</p>	+150
34.00	<p>Creek, 20 lks. wide, one line course NW</p> <p>Ascend</p>	-200
40.00	<p>A fir, 10 ins. diam., which I marked $\frac{1}{4}$ S on W. face for $\frac{1}{4}$ sec. cor., from which</p> <p style="padding-left: 40px;">A fir, 6 ins. diam. bears N.53*E., 17 lks. dist. marked $\frac{1}{4}$ S B T.</p> <p style="padding-left: 40px;">A fir, 10 ins. diam., bears S.45*W., 10 lks. dist., marked $\frac{1}{4}$ S B T.</p>	
50.75	<p>Top of ridge, course NE and SW</p>	+200