

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 21 S., R. 9 W.

CHAINS		
	Pass over spur	
35.92	Creek 4 lks, wide Course S. Ascend	
40.36	Set sand stone 14 x 12 x 6 ins. 10 ins. in the ground on steep hill side sloping E. for $\frac{1}{4}$ Sec. Cor. Marked $\frac{1}{4}$ on the N. face, from which A Fir, 60 ins. diam. bears N. $68\frac{1}{2}^{\circ}$ W., 137 lks. dist. marked $\frac{1}{4}$ S B T. A Hemlock, 6 ins. diam. bears S. $47^{\circ}45'$ W., 63 lks. dist. marked $\frac{1}{4}$ S. B T.	
54.00	Top of ridge Course NE and SW Pass over cone.	+125
66.00	Top of ridge Course NW and SE Descend	
78.16	Creek 10 lks. wide Course S. $60^{\circ}$ W. Ascend	-250
78.46	A Cedar 75 ins. diam. a line tree marked with 2 notches on the E. and W. sides	
80.72	The Cor. to Secs. 14, 15, 22 and 23 Land, mountainous 80.72 chs. Soil, 2nd rate Timber, fir, hemlock, cedar and alder Dense undergrowth of hemlock, fir, vine maple, salal-berry, fern, flag and huckleberry 80.72 chs. September 11, 1894	+50
North, $002^{\circ}$ W. Bet. Secs. 14 and 15 <span style="float: right;">Va. <math>20^{\circ}</math> E.</span>		
	Pass over spur	
7.60	Creek 1 lk. wide Course E. Ascend	
14.75	Top of ridge Course E. and W. Descend	+100
25.75	Creek 1 lk. wide Course East Ascend	-150