

64
County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 21 S., R. 9 W.

CHAINS	<p>$\frac{1}{2}$ S. on W. face, from which</p> <p style="padding-left: 40px;">A fir, 42 ins. diam. bears N.8°E., 88 lks. dist. Marked $\frac{1}{2}$ S. B T.</p> <p style="padding-left: 40px;">A Cedar, 10 ins. diam. bears N.32°W., 83 lks. dist. Marked $\frac{1}{2}$ S. B T.</p> <p>56.75 Top of ridge, Course NE. and SW. +100</p> <p>Descend</p> <p>72.00 Creek, 5 lks. wide, Course N.75°E.</p> <p>Ascend</p> <p>80.00 Set Sand Stone 18 x 9 x 8 in. 14 ins. in the ground on steep hill side sloping South for Cor. to Secs. 9, 10, 15 and 16, marked with 4 notches on the S. and 3 notches on the E. sides, from which</p> <p style="padding-left: 40px;">A madrone, 5 ins. diam. bears N.25°30'E., 75 lks. dist. Marked T 21 S R 9 W S 10 B T.</p> <p style="padding-left: 40px;">A d. fir, 16 ins. diam. bears S.82°30'E., 8 lks. dist. Marked T 21 S R 9 W S 15 B T.</p> <p style="padding-left: 40px;">A fir, 36 ins. diam. bears S.2°W., 212 lks. dist. Marked T 21 S R 9 W S 16 B T.</p> <p style="padding-left: 40px;">A d. fir, 8 ins. diam. bears N.57°W., 31 lks. dist. Marked T 21 S R 9 W S 9 B T.</p> <p>Land, broken and mountainous 80.00 chs.</p> <p>Soil, 3rd rate.</p> <p>Timber, fir, cedar, hemlock, maple and alder.</p> <p>Dense undergrowth of fir, hemlock, maple, thimble berry salmon and salalberry, willow, hazel and rhododendron 80.00 chs.</p> <p style="text-align: right;">September 18, 1894.</p>
	<p>S., 89°49'E. on random line</p> <p>Bet. Secs. 10 and 15</p> <p style="text-align: right;">Va. 20°E.</p> <p>40.00 Set temporary $\frac{1}{4}$ Sec. Cor.</p> <p>79.80 Intersected N. and S. line 38 lks. North of Cor. to</p>