

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 21 S., R. 9 W.

CHAINS		
	Land, mountainous 108.77 chs. Soil, 3rd rate. Timber, fir, hemlock, cedar, alder, maple and cherry. Dense undergrowth of vine maple, hemlock, thimble and salmonberry, arrow-wood, alder, salal-berry, hemlock and fir 108.77 chs. <p style="text-align: right;">September 20, 1894.</p>	
	From Cor. to Secs. 32 and 33 and on the South Bdy. of Tp. Thence I run N., 0.03'W. bet. Secs. 32 and 33. <p style="text-align: right;">Va.20'E.</p>	
	Ascend	
3.00	Top of ridge sloping SW.	+50
	Descend	
10.08	Creek, 2 lks. wide, Course SW.	-200
	Ascend steep hill	
22.25	Top of ridge, Course E. and W.	+500
	Descend	
31.00	Creek, 2 lks. wide, Course E.	
	Pass over spur	
40.00	Set Sand Stone 14 x 12 x 8 ins. 10 ins. in the ground for $\frac{1}{4}$ Sec. Cor. marked $\frac{1}{4}$ on the W. side, from which A fir, 6 ins. diam., bears N.84*15'E., 78 lks.dist. marked $\frac{1}{4}$ S. B T. A fir, 48 ins. diam. bears N.21*15'W., 24 lks.dist. marked $\frac{1}{4}$ S B T.	
43.90	Creek, 2 lks. wide, Course E.	-150
	Pass over spur	
52.00	Creek, 4 lks. wide, Course E.	
	Ascend	
60.85	Top of ridge Course E. and W.	+125
	Descend	
65.50	Creek, 3 lks. wide, course S.E.	-100