

## Subdivisions of T. 21 S., R. 9 W.

CHAINS 60.00	Leave spur.	
82.25	Creek, 4 lks. wide, Course N.60°E. Pass over spur.	-600
93.50	Creek, 1 lk. wide, runs E. Pass over spur.	
107.70	Creek, 2 lks. wide Course E. Ascend,	
112.14	To a point 27.03 chs. N.89°33'E. of the SE. corner of Sec. 5 set alder post 4½ ft. long, 4 ins. sq., 24 ins. in the ground at the point of intersection on hill side sloping E. and on west side of large cedar log for closing corner to Secs. 8 and 9 Marked C C T 21 S R 9 W on the S., S 9 on the E. and S 8 on the W. faces with 5 grooves on the S. and 4 grooves on the E. faces, from which  A fir, 36 ins. diam., bears S.65°30'E., 160 lks. dist. marked T 21 S R 9 W S 9 B T.  An alder, 8 ins. diam., bears S.66°30'W., 10 lks. dist. marked T 21 S R 9 W S 8 B T.  A cherry, 6 ins. diam., bears N.14°E., 33 lks. dist. marked C C T 21 S R 9 W S 8 and 9 B T.  Land, mountainous 112.14 chs.  Soil, 2nd and 3rd rate.  Timber, scattering fir, hemlock and cedar.  Dense undergrowth of hemlock, fir, thimbleberry, alder, manzanita, mountain balm and arrow-wood 112.14 chs.	
	Commenced at the SE. corner of Sec. 5 which is a rock in place 40 x 24 x 10 ins. above ground on steep hill side sloping SW. marked with a X on top of stone, the other marks had been scaled off by a large tree falling on it. I remarked stone with 5 notches on the S. and 4 notches on the E. edges, from which	