

Resurvey East Boundary, T. 21 S., R. 10 W.

CHAINS  
 4.50 Ravine, course SW.; ascend S. slope 220 ft. to  
 13.10 Top of ridge, bears NW. and SE.; descend gradually along  
 E. slope 60 ft. to  
 28.06 Set an iron post, 3 ft. long, 2 ins. diam., 24 ins. in the  
 ground, for cor. of secs. 13 and 24, with brass cap  
 marked

T21S  
 S13  
 S24  
 R10W  
 1919

from which

An alder, 8 ins. diam., bears S.83 $\frac{1}{2}$ \*W., 35 lks. dist.,  
 marked T 21 S R 10 W S 24 B T.

A fir, 36 ins. diam., bears N.52\*W., 17 lks. dist.,  
 marked T 21 S R 10 W S 13 B T.

Land, mountainous.

Soil, sandy loam, shallow on sandstone subsoil; 2nd rate.

Timber, fir and alder.

Undergrowth, salal, huckleberry, salmonberry and vine-  
 maple.

N.1\*03'E., resurveying the E. bdy. of sec. 13.

Descend along E. slope, through heavy timber and scattering  
 undergrowth, 200 ft. to

11.02 Intersect the old  $\frac{1}{4}$  sec. cor., which is a sandstone, firm-  
 ly set, marked and witnessed as described by the sur-  
 veyor general. I obliterate marks on the old bearing  
 tree referring to sec. 13 and change this cor. to refer  
 to sec. 18 only and alongside the old cor. set an iron  
 post, 3 ft. long, 1 in. diam., 26 ins. in the ground,  
 for  $\frac{1}{4}$  sec. cor. of sec. 18 only, with brass cap marked

†  
 S18  
 1919

from which