

Subdivisions of T. 21 S., R. 10 W.
 As surveyed by John W. Meldrum, Deputy Surveyor,
 under Contract No. 116, dated December 12, 1866.

CHAINS		
	South, between Secs. 3 and 4.	Va.19*E.
40.00	Set post for $\frac{1}{4}$ Sec. corner from which A Fir, 5 ins. diam., bears N.20*E., 6 lks. dist., A Maple, 8 ins. diam., bears N.80*W., 20 lks. dist.,	
80.00	Set stone, 24x12x12 for corner to Secs. 3, 4, 9 and 10. A Hemlock, 8 ins. diam., bears N.83*E., 34 lks. dist.	+300
	Land, very rough and broken. Soil, 3rd rate. Timber, Hemlock and Fir. Dense undergrowth of small Hemlock.	
	Feb. 20th, 1867.	
<hr/>		
	West, between Secs. 4 and 9.	Va.19*E.
40.00	Set a Fir post, for $\frac{1}{4}$ Sec. corner, from which A Fir, 24 ins. diam., bears S.25*E., 3 lks. dist. A Fir, 10 ins. diam., bears N.42*W., 21 lks. dist.	
56.00	Foot of hill.	-300
60.70	Creek 5 lks. wide, runs Southwest.	
72.80	Same creek, runs Northwest.	
80.00	Set stone, 24x18x12 for corner to Secs. 4, 5, 8 and 9, from which An Alder, 12 ins. diam., bears N.12*E., 37 lks. dist.	
	Land, rough and broken. Soil, 3rd rate. Timber, Hemlock and Fir.	
	Feb. 21st, 1867.	
<hr/>		
	North, on a random line bet. Secs. 4 and 5.	Va.19*E.
40.00	Set temp. $\frac{1}{4}$ Sec. corner.	
79.80	Intersect North boundary at corner to Secs. 4 and 5, from which I run	