

RESURVEY EAST BOUNDARY T. 21 S., R. 10 W.

CHAINS

from which

A Fir, 30 ins. diam., bears N.84*E., 68 lks.
dist., marked T 21 S R 9 W S 18 B T (New B.T.)

A Fir, 36 ins. diam., bears S.62*E., 36 lks.
dist., marked T 21 S R 9 W S 19 B T (Old B.T.)

From this cor.

N.1*03'E., resurveying the E. bdy. of Sec. 24.

Continue ascent of S. slope 95 ft. to

- 1.90 Top of spur, slopes SW.; descend NW slope 90 ft. to
- 4.50 Ravine, course SW.; ascend S. slope 220 ft. to
- 13.10 Top of ridge, bears NW and SE.; descend gradually along
E. slope 60 ft. to
- 28.06 Set an iron post, 3 ft. long, 2 ins. diam., 24 ins. in
the ground, for cor. of Secs. 13 and 24, with brass
cap marked

T21S
S13
S24
R10W
1919

from which

An Alder, 8 ins. diam., bears S.83 $\frac{1}{2}$ *W., 35 lks.
dist., marked T 21 S R 10 W S 24 B T.

A Fir, 36 ins. diam., bears N.52*W., 17 lks.
dist., marked T 21 S R 10 W S 13 B T.

Land, mountainous,

Soil, sandy loam, shallow on sandstone subsoil; 2nd rate.

Timber, Fir and Alder.

Undergrowth, Salal, Huckleberry, Salmonberry and Vine-
maple.

N.1*03'E., resurveying the E. bdy. of Sec. 13.

Descend along E. slope, through heavy timber and
scattering undergrowth, 200 ft. to

- 11.02 Intersect the old $\frac{1}{4}$ Sec. cor., which is a sandstone,
firmly set, marked and witnessed as described by the