

RESURVEY SOUTH BOUNDARY T. 21 S., R. 10 W.

CHAINS

Soil, sandy loam and vegetable mold; 1st rate.

Timber, Fir and Alder.

Undergrowth, Salmonberry, Vinemaple and Salal.

N.88*11'W., resurveying the S. bdy, of Sec. 36.

Ascend E and SE slopes, through heavy timber and scattering undergrowth, 590 ft. to

38.93 Intersect the old $\frac{1}{4}$ Sec. cor., which is a decayed post, marked and witnessed as described by the Surveyor General. The old bearing trees are dead. Alongside the old cor. set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground, for $\frac{1}{4}$ Sec. cor. of Sec. 1 only, with brass cap marked

$\frac{1}{4}$ S1
1919

from which

A Fir, 8 ins. diam., bears S.11*E., 44 lks. dist. marked $\frac{1}{4}$ S 1 B T (New B.T.)

A Fir, 8 ins. diam., bears S.35*W., 40 lks. dist. marked $\frac{1}{4}$ S 1 B T (New B.T.)

From this corner

S.88*26'W., resurveying the S. bdy. of Sec. 36.

Ascend SE slope 75 ft. to

5.27 (A point 40.00 chs. easterly from the cor. of Secs. 35 and 36)

Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground, for $\frac{1}{4}$ Sec. cor. of Sec. 36 only, with brass cap marked

$\frac{1}{4}$ S36
1919

from which

A Fir, 8 ins. diam., bears N.24*E., 38 lks. dist., marked $\frac{1}{4}$ S 36 B T.

A Fir, 6 ins. diam., bears N.65*W., 21 lks. dist., marked $\frac{1}{4}$ S 36 B T.