

RESURVEY SOUTH BOUNDARY T. 21 S., R. 10 W.

CHAINS

shallow in many places; 2nd rate.

Timber, Fir and Alder.

Undergrowth, Salmonberry, Vinemaple and Salal.

N.89°37'W., resurveying the S bdy. of Sec. 35.

Ascend NE slope, through small timber and dense undergrowth, 85 ft. to

2.65 Summit of ridge, bears NW and SE; descend steep SW slope 400 ft. to

19.65 Ravine, course S; ascend SE slope 100 ft. to

22.40 Top of small spur, slopes SE; descend along S. slope 35 ft. to

23.90 Bottom of descent; ascend SE slope 50 ft. to

26.95 Top of ascent; descend SW slope 200 ft. to

31.65 Ravine, course SW; ascend steep SE slope 35 ft. to

32.82 Intersect the old $\frac{1}{4}$ Sec. cor. which is a Fir snag, marked and witnessed as described by the Surveyor General. I change this corner to refer to Sec. 2 only and alongside the old cor. set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground, for $\frac{1}{4}$ cor. of Sec. 2 only, with brass cap marked

$\frac{1}{4}$
S2
1919

from which

A Fir, 8 ins. diam., bears S.5°W., 15 lks. dist. marked $\frac{1}{4}$ S 2 B T (New B.T.)

A Fir, 16 ins. diam., bears S.73°W., 12 lks. dist., marked $\frac{1}{4}$ S 2 B T (Old B.T.)

From this corner

S.88°47'W., resurveying the S. bdy. of Sec. 35.

Ascend E. slope 210 ft. to

5.60 Top of spur, slopes SE; thence along S. slope.

7.18 Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground, for $\frac{1}{4}$ Sec. cor. of Sec. 35 only, with