

RESURVEY SOUTH BOUNDARY T. 21 S., R. 10 W.

CHAINS

- 3.20 Creek, 5 lks. wide, course N; ascend E slope 125 ft. to
 5.90 Top of spur, slopes N; descend NW slope 105 ft. to
 9.90 Ravine, course N; ascend E slope 185 ft. to
 14.20 Top of spur, slopes N; descend W slope 145 ft. to
 17.90 Bottom of descent; ascend NE slope 150 ft. to
 23.30 Top of spur, slopes N; descend NW slope 60 ft. to
 28.70 Bottom of descent; thence along N slope.
 31.00 Top of ridge, bears NW and SE; descend SW slope 400 ft.
 to
 40.00 Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in
 the ground, for $\frac{1}{4}$ sec. cor. of Sec. 31 only, with brass
 cap marked
- $\frac{1}{4}$ S31
 1919
- from which
- A Hemlock, 36 ins. diam., bears N.2*E., 44 lks.
 dist., marked $\frac{1}{4}$ S 31 B T.
- A Fir, 40 ins. diam., bears N.60*W., 29 lks.
 dist., marked $\frac{1}{4}$ S 31 B T.
- Continue descent 50 ft. to
- 42.90 Intersect the old $\frac{1}{4}$ sec. cor. of Sec. 6, which is a Fir,
 26 ins. diam., marked and witnessed as described by
 the Surveyor General. This cor. is identical with
 cor. No. 1, H.E.S. No. 130.
- From this corner
- S.88*32'W., resurveying the S boundary of Sec. 31.
- Descend W slope 100 ft. to
- 2.00 Foot of descent; thence across bottom land; leave dense
 undergrowth.
- 3.33 Intersect cor. N. 12, H.E.S. No. 130, which is a stone,
 firmly set, marked and witnessed as described by the
 Surveyor General.
- 3.64 Intersect cor. No. 13, H.E.S. No. 130, which is a stone,
 firmly set, marked and witnessed as described by the
 Surveyor General.