

RESURVEY SOUTH BOUNDARY T. 21 S., R. 10 W.

CHAINS

6.80 Road, bears NE and SW.

9.55 Left bank of Harvey Creek, course SW.

16.40 Right bank of Harvey Creek; ascend SE slope.

17.58 Intersect cor. No. 25 H.E.S. No. 130, which is a stone, firmly set, marked and witnessed as described by the Surveyor General.

23.30 Top of spur, 280 ft. above creek, slopes SE; continue ascent 235 ft. to

29.10 Top of ridge, bears N and S; descend.

29.81 Apportioned distance

Set an iron post, 3 ft. long, 3 ins. diam., 24 ins. in the ground, for closing cor. of Tps. 21 S., Rs. 10 and 11 W., with brass cap marked

CC	
T21S	
R11W	R10W
S36	S31

1919

F.P. OK
 8/85
 BY JAMES BROCKMAN
 MISS 21
 A+B

from which

A Fir, 12 ins. diam., bears N.66*E., 25 lks. dist., marked C C T 21 S R 10 W S 31 B T.

A Fir, 10 ins. diam., bears N.70*W., 7 lks. dist., marked C C T 21 S R 11 W S 36 B T.

Thence along S bdy. of Sec. 36, T. 21 S., R. 11 W.

Continue descent.

36.10 Stream, 4 lks. wide, course SW., 250 ft. below ridge; ascend 20 ft. to

38.00 Stream, 2 lks. wide, course SE; continue ascend 20 ft. to

38.50 Intersect the cor. of Tps. 22 S., Rs. 10 and 11 W., which is a stone, firmly set, marked and witnessed as described by the Surveyor General.

Land, mountainous.

Soil, shallow sandy loam on sandstone base; 2nd and 3rd rate.

Timber, Fir, Hemlock, Alder and Maple.