

RESURVEY PORTION WEST BOUNDARY T. 21 S., R. 10 W.

CHAINS

A Maple, 12 ins. diam., bears N.80*E., 50 lks. dist., marked $\frac{1}{4}$ S 31 B T.

A Maple, 12 ins. diam., bears S.71*E., 138 lks. dist., marked $\frac{1}{4}$ S 31 B T.

48.85 Bear Creek, 15 lks. wide, course E; ascend SE slope 415 ft. to spur.

49.65 Intersect bdy. of H.E.S. No. 130, S.82*22'W., 51 lks. from cor. No. 18, which is a stone, firmly set, marked and witnessed as described by the Surveyor General.

72.50 Top of spur, slopes E; descend NE slope 375 ft. to

88.72 Set an iron post, 3 ft. long, 2 ins. diam., 24 ins. in the ground, for cor. of Secs. 30 and 31, with brass cap marked

T21S
S30

S31
R10W
1919

from which

An Alder, 10 ins. diam., bears N.73*E., 16 lks. dist., marked T 21 S R 10 W S 30 B T.

A Maple, 12 ins. diam., bears S.41*E., 56 lks. dist., marked T 21 S R 10 W S 31 B T.

Land, mountainous.

Soil, shallow sandy loam and vegetable mold; 2nd and 3rd rate.

Timber, Fir, Hemlock, Maple and Alder.

Undergrowth, Salmonberry, Vinemaple and Salal.

N.0*06'W, resurveying the W. bdy. of Sec. 30.

Over mountainous land, through heavy timber and dense undergrowth, over creek bottom.

0.20 Cedar Creek, 10 lks. wide, course SE; ascend S. slope 180 ft. to

6.50 Top of spur, slopes SW; along W. slope.