

## SUBDIVISIONS, T. 21 S., R. 10 W.

CHAINS

39.60 Intersect the old  $\frac{1}{4}$  Sec. cor., which is a stone, loosely set, marked and witnessed as described by the Surveyor General. Alongside the old stone set an iron post, 3 ft. long, 1 in. diam., .26 ins. in the ground, for  $\frac{1}{4}$  sec. corner, with brass cap marked

$$\frac{\frac{1}{4} S6}{S7}$$

1919

from which

A Fir, 34 ins. diam., bears N.30\*W., 17 lks. dist., marked  $\frac{1}{4}$  S 6 B T.

A Fir, 40 ins. diam., bears S.65\*W., 7 lks. dist., marked  $\frac{1}{4}$  S 7 B T (Old B.T.)

From this  $\frac{1}{4}$  Section corner

S.88\*17'E., resurveying the line bet. Secs. 6 and 7.

Ascend SW slope 175 ft. to

7.85 Top of ridge, bears NW and SE; descend along broken N slope 115 ft. to

13.90 Foot of descent; ascend NW slope 80 ft. to

17.40 Top of spur, slopes N; descend NE slope 160 ft. to

24.80 Small stream, 1 lk. wide, course N; ascend NW slope 225 ft. to

28.85 Top of spur, slopes N; descend NE slope 265 ft. to

38.00 Ravine, course N; ascend NW slope 50 ft. to

40.10 The corner of Secs. 5, 6, 7 and 8.

Land, mountainous.

Soil, rocky, 4th rate.

Timber, Fir, Cedar and Hemlock.

Undergrowth, Huckleberry, Vinemaple, Salal, Currant, Arrowwood, Cherry, Salmonberry and Fern.

---

 GENERAL DESCRIPTION
 

---

The land in this township is rough and mountainous, broken by innumerable ravines, gulches and small