

The East Boundary of T. 21 S., R. 12 W.,
as surveyed by Harvey Gordon, Deputy Surveyor, under Contract No. 69,
dated Feb. 2, 1857.

CHAINS

North, on E. bdy. of sec. 36.

Beginning at post on S. side of River at "S.34*29'" on
E. bdy. of sec. 1, thence

Base S.69*E. 4.50 chs.

S.77 $\frac{1}{2}$ *E. 6.70 chs.

S.89*E. 9.10 chs.

Angle opposite 22*30' distance across 44.68 chs.

10.39 To right bank of Umpqua River.

Set post, from which

A spruce, 10 ins. diam., bears N.15*E., 62 lks. dist.

A spruce, 8 ins. diam., bears N.31*W., 77 lks. dist.

39.50 Left bank of Butler's Creek set post, from which

A spruce, 15 ins. diam., bears S.4*E., 370 lks. dist.

A spruce, 30 ins. diam., bears S.5*W., 412 lks. dist.

Base W. 50 lks. angle opposite 15*45', dist. 180 lks.

40.00 $\frac{1}{2}$ sec. cor. is a creek.

41.30 Set post on right bank, from which

A spruce, 4 ins. diam., bears N.49*W., 72 lks. dist.

A spruce, 6 ins. diam., bears N.19*E., 117 lks. dist.

North of Butler's Creek the mountains are too high,
steep and brushy to be surveyed.

Began at SW. cor. of sec. 36, thence

Ran North 80.00

and East 80.00

To the cor. of secs. 25, 30, 31 and 36.

80.00 Set post, from which

A cedar, 50 ins. diam., bears S.4*E., 52 lks. dist.

A cedar, 50 ins. diam., bears S.20*W., 26 lks. dist.

A cedar, 6 ins. diam., bears N.81*W., 66 lks. dist.

A fir, 30 ins. diam., bears N.36*E., 90 lks. dist.

S. $\frac{1}{2}$ mile, level, soil 1st rate.

N. $\frac{1}{2}$ miles, mountainous, soil unfit for settlement or
cultivation.

Timber, spruce and fir.

October 11, 1857.