

## Subdivisions in T. 21 S., R. 11 W.

CHAINS	
63.46	Set meander post on left bank, from which A crab apple, 5 ins. diam., bears S.20*E., 247 lks. dist. An alder, 7 ins. diam., bears S.3*W., 621 lks. dist.
80.00	Set stone, 16x12x8 ins., on steep rocky hill side for cor. to secs. 20, 21, 28 and 29, from which An alder, 4 ins. diam., bears N.67*W., 38 lks. dist. Land on N. $\frac{1}{2}$ level, soil, 1st rate; on S. $\frac{1}{2}$ broken and stony, soil 3rd rate. Timber, hemlock, fir, cedar and alder. Thick undergrowth of vine maple. Jan. 4, 1867.
	East, on a true line bet. secs. 21 and 28. Va. 19*E.
23.90	Creek, 65 lks. wide, runs NW.
40.00	Set post for $\frac{1}{4}$ sec cor., from which A willow, 4 ins. diam., bears S.50*E., 71 lks. dist. A spruce, 5 ins. diam., bears N.38*E., 134 lks. dist.
43.75	Steep and rugged mountain, impracticable to survey. Soil, 1st rate, land, level. Timber, cedar, fir and alder. Very thick undergrowth of vine maple.
	East, on a true line bet. secs. 16 and 21. Va. 19*E.
40.00	Set $\frac{1}{4}$ sec. post, from which A maple, 15 ins. diam., bears S.86*W., 106 lks. dist. An alder, 18 ins. diam., bears N.10*E., 11 lks. dist. Intersect rough mountain at this point. Land, level, soil, 1st rate. Jan. 6th