

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 21 S., R. 11 W.

CHAINS		
	West, on random, bet. secs. 19 and 30.	
	Va.19*52'E.	
40.00	Set temp. $\frac{1}{4}$ sec. cor.	
79.20	Intersect W bdy. of tp.; the cor. to secs. 24, 25, 19 and 30, having been destroyed, also the bearing trees, to wit, a vine maple, 2 ins. diam., and an elder, 4 ins. There is a maple answering the description, but no marks can be found on the same.	
	<p>I, therefore, go to $\frac{1}{4}$ sec. cor. bet. secs. 19 and 24, which is a post, 4 ins. sq., marked $\frac{1}{4}$ S on W face, (I think, set lately by the Co. Surveyour) from which</p> <p>A spruce, 10 ins. diam., bears S.46*W., 40 lks. dist., marked $\frac{1}{4}$ \odot B T.</p> <p>A hemlock, 36 ins. diam., bears S.9*E., 20 lks. dist., marks have been cut out lately.</p> <p>(Called erroneously a spruce in the field notes of former survey.)</p> <p>Thence I run</p> <p>South, on West bdy. of sec. 19.</p> <p style="text-align: right;">Va.19*42'E.</p> <p>Ascend N slope.</p>	
5.00	A ridge, bears \odot E and NW.	+120
12.75	A canyon, course NW; begin ascent of NW slope.	-80
18.25	Top of spur, bears NW and SE.	+100
32.00	A canyon, course NW; begin steep ascent.	+250
40.00	Set a sandstone, 15x8x6 ins. 10 ins. in the ground, for cor. to secs. 24, 25, 19 and 30, marked with 2 notches on S and 4 notches on N edges, from which	
	A wh. fir, 6 ins. diam., bears S.61 $\frac{1}{2}$ *W., 12 lks. dist., marked T 21 \odot R 12 W S 25 B T.	
	A fir, 12 ins. diam., bears S.51*E., 25 lks. dist., marked T 21 \odot R 11 W S 30 B T.	