

## Subdivisions of T. 21 S., R. 11 W.

## CHAINS

The var. in the South is  $19^{\circ}45'E.$ , increasing toward the Northwest to  $20^{\circ}10'E.$

The underlying rock is a soft sandstone, which, when fully exposed to atmospheric influences crumbles easily.

There are two settlers in sec. 28 and one each in secs. 8, 10, 15, 22, 23, 29, 30, 31 and 35.

North Boundary of T. 22 S., R. 11 W.  
As surveyed by Williams R. Whipple, Deputy Surveyor  
Under contract No. 612, April 28, 1893.

In subdividing this township, I was unable to find the cor. to secs. 4, 5, 32 and 33 on the N bdy. I found the cor. to secs. 3, 4, 33 and 34, which is a post, 4 ins. sq., marked T 21 S S 34 on NE., T 22 S S 3 on SE., R 11 W S 4 on SW., S 33 on NW faces, with 3 notches on E and W edges, from which

A willow, 8 ins. diam., bears  $S.42\frac{1}{2}^{\circ}E.$ , 45 lks. dist., marked T 22 S R 11 W S 3 B T.

A fir, 30 ins. diam., bears  $N.21^{\circ}W.$ , 31 lks. dist., marked T 22 S R 11 W S 33 B T.

The other bearing trees are gone.

From this cor. I run

West, bet. secs. 4 and 33.

Va.  $20^{\circ}15'E.$

over N slope.

10.50 A brook, 4 lks. wide, course N.

16.75 A brook, 2 lks. wide, course N.

20.10 A brook, 2 lks. wide, course N.

27.50 A brook, 3 lks. wide, course N.

37.90 A brook, 6 lks. wide, course N.

40.00 A this point, I make a thorough search for the  $\frac{1}{4}$  sec. cor. which is described as a post with bearing trees but find no trace of the same.