

This

Subdivisions of T 22 S. R 4 W. W.M.

CHAINS

North bet. secs. 10 and 11.

Vs. 21½\*E.

Descend mountain slope, 25\*

40.00 Set post, 4 ins. diam., 4 ft. long with marked stone, 12 ins. in ground for qr. sec. cor.; marked ¼ S on W face from which

A Fir, 40 ins. diam., bears S.10\*W., 3 lks. dist., marked ¼ S B T.

A Fir, 14 ins; diam., bears N.80\*E., 5 lks. dist., marked ¼ S B T.

41.50 Branch, 1 lk. wide, flows W. ascend 30\*.

50.00 Top of hill, descend 22\*.

80.00 Set post, 6 ins. diam., 4 ft. long with marked stone, 12 ins. in the ground for cor to sec. 2, 3, 10 11, marked T 22 S S 2 on NE., R 4 W S 11 on SE., S 10 on S W., S 3 on NW face, with 2 notches on E and 5 in S edges, from which

A Fir, 46 ins. diam., bears N.70\*W., 8 lks. dist., marked T 22 S R 4 W S 3 B T.

A Fir, 48 ins. diam., bears S.35\*W., 7 lks. dist., marked T 22 S R 4 W S 10 B T.

A Maple, 10 ins. diam., bears N.14\*E., 41 lks. dist., marked T 22 S R 4 W S 2 B T.

A Maple, 10 ins. diam., bears S.25\*E., 47 lks. dist., marked T 22 S R 4 W S 11 B T.

Land exceedingly rough.

Soil poor, 3rd rate.

Timber fir and oak.

Thick undergrowth of hazel, 80.00 chs.

From the precipitous character of the country between secs. 2 and 11, I did not run this line.