

Subdivisions of T 22 S., R 4 W., W.M.

CHAINS

West on random line bet. secs. 26 and 35.

Va. $20\frac{1}{2}$ *E.

40.00 Set temp. qr. sec. cor.

80.30 Intersect N and S line, 70 lks. South of cor. to secs. 26, 27, 34 and 35, which is a post, 4 ins. diam., in ground marked T 22 S S 26 on NE., R 4 W S 35 on SE., S 34 on SW., S 27 on NW face, from which

A Fir, 12 ins. diam., bears N.14*E., 15 lks. dist., marked T 22 S R 4 W S 26 B T.

A Fir, 10 ins. diam., bears N.20*W., 27 lks. dist., marked T 22 S R 4 W S 27 B T.

A Fir, 12 ins. diam., bears S.82*W., 165 lks. dist., marked T 22 S R 4 W S 34 B T.

A Laurel, 6 ins. diam., bears S.20*E., 39 lks. dist., marked T 22 S R 4 W S 35 B T.

S.89*30'E., on true line bet. secs. 26 and 35.

Ascend 20*

5.00 Top of ridge, descend 20*.

38.00 Branch, 1 lk., flows south, ascend 25*

40.15 Set post, 4 ins. diam., 4 ft. long, with marked stone, 12 ins. in ground for qr. sec. cor., marked $\frac{1}{2}$ S on N face from which

A Fir, 8 ins. diam., bears N.82*W., 19 lks. dist., marked $\frac{1}{2}$ S B T.

A Laurel, 5 ins. diam., bears S.30*E., 10 lks. dist., marked $\frac{1}{4}$ S B T., Still ascend.

80.30 The cor. to secs. 25, 26, 35 and 36.

Land rough, mountain. Soil poor, rocky.

Dense fir and cedar timber, thick undergrowth of hazel and vinemaple, 80.30 chs.

North bet. secs. 25 and 26.

Va. $20\frac{1}{2}$ *E.

Descend 15* slope.

40.00 Set post, 4 ins. diam., 4 ft. long, with marked stone, 12 ins. in ground for qr. sec. cor., marked $\frac{1}{4}$ S on W face.