

Subdivisions of T 22 S., R 4 W., W.M.

CHAINS

from which

A Spruce, 15 ins. diam., bears N.34 $\frac{1}{2}$ *W., 72 lks. dist., marked $\frac{1}{2}$ S B T.

A Spruce, 14 ins. diam., bears S.25*E., 67 lks. dist., marked $\frac{1}{2}$ S B T.

70.00 Spring. Slope 20*, still descend.

80.00 Set post, 6 ins. diam., 4 ft. long, with marked stone, 12 ins. in ground for cor. to secs. 23, 24, 25 and 26, marked T 22 S S 24 on NE., R 4 W S 25 on SE., S 26 on SW., S 23 on NW face, with 1 notch on E and 2 on S edges, from which

A Cedar, 8 ins. diam., bears N.23*W., 45 lks. dist. marked T 22 S R 4 W S 23 B T.

A Fir, 24 ins. diam., bears N.32*E., 24 lks. dist., marked T 22 S R 4 W S 24 B T.

A Hemlock, 10 ins. diam., bears S.28*E., 30 lks. dist., marked T 22 S R 4 W S 25 B T.

A Cedar, 10 ins. diam., bears S.4*W., 54 lks. dist. marked T 22 S R 4 W S 26 B T.

Land steep mountain side. Soil poor, thin.

Dense fir, cedar, spruce and hemlock timbers.

Undergrowth, hazel, 80.00 chs.

East on random line bet. secs. 24 and 25.

Va. 18 $\frac{1}{2}$ *E.

40.00 Set temp. qr. sec. cor.

79.60 Intersect East boundary of Tp., 70 lks. North of cor. to secs. 19, 30, 24 and 25, which is a post, 4 ins. diam. in ground marked T 22 S S 19 on NE., R 3 W S 30 on SE. R 4 W S 25 on SW., S 24 on NW face, from which

A Fir, 20 ins. diam., bears N.3*E., 175 lks. dist., marked T 22 S R 3 W S 19 B T.

A Fir, 28 ins. diam., bears N.3*W., 125 lks. dist., marked T 22 S R 4 W S 24 B T.