

Subdivisions of T 22 S., R 4 W., W.M.

CHAINS

A Fir, 24 ins. diam., bears S.40*W., 87 lks. dist.,
marked T 22 S R 4 W S 25 B T.

A Fir, 12 ins. diam., bears S.45*E., 312 lks. dist.,
marked T 22 S R 3 W S 30 B T.

Thence I run

N.89*30'W., on true line bet. secs. 24 and 25.

Ascend 15* slope on East slope of mountain.

39.80 Set post, 4 ins. diam., 4 ft. long, with marked stone, 12
ins in ground for $\frac{1}{2}$ sec. cor., marked $\frac{1}{2}$ S on N face,
from which

A Laurel, 6 ins. diam., bears N.14*W., 50 lks. dist.,
marked $\frac{1}{2}$ S B T.

A Fir, 36 ins. diam., bears S.3*E., 130 lks. dist.,
marked $\frac{1}{2}$ S P T.

73.00 Branch, 3 lks. wide, flows SE., still ascend.

79.60 The cor. to secs. 23, 24, 25 and 26.

Land rough mountain side, soil poor, rocky.

Timber, fir, cedar and hemlock.

Thick undergrowth of hazel, 79.60 chs.

West on random line bet. secs. 23 and 26.

Va. $18\frac{1}{2}$ *E.

40.00 Set temp. gr. sec. cor.

80.75 Intersect N and S line, 75 lks. South of cor. to secs.
22, 23, 26 and 27, which is a post, 4 ins. diam.,
marked T 22 S S 23 on NE., R 4 W S 26 on SE., S 27 on
SW., S 22 on NW face, from which

A Fir, 60 ins. diam., bears S.70 $\frac{1}{2}$ *E., 21 lks. dist.,
marked T 22 S R 4 W S 26 B T.

A Hemlock, 24 ins. diam., bears S.61*W., 23 lks.
dist., marked T 22 S R 4 W S 27 B T.

A Fir, 52 ins. diam., bears N.19 $\frac{1}{2}$ *W., 41 lks. dist.,
marked T 22 S R 4 W S 22 B T.

A Fir, 8 ins. diam., bears N.26'E., 11 lks. dist.,
marked T 22 S R 4 W S 23 B T.