

Subdivisions of T 22 S., R 4 W., W.M.

CHAINS

Thence I run

S.89*28'East on true line bet. secs. 23 and 26.

Descend 15* slope.

10.00 Foot of hill, ascend 10*

14.00 Mr. Chamberlain's Cabin bears North about 500

22.00 Top of ridge, descend 20*

31.00 Branch, 1 lk., flows NE., ascend 25*

40.37 Set post, 4 ins. diam., 4 ft. long, with marked stone, 12 ins. in ground for qr. sec. cor., marked $\frac{1}{4}$ S on N face from which

A Fir, 40 ins. diam., bears S.80*E., 54 lks. dist., marked $\frac{1}{4}$ S B T.

A Fir, 5 ins. diam., bears N.89*W., 43 lks. dist., marked $\frac{1}{4}$ S B T.

57.00 Top of hill, descend 27*

80.75 The cor. to secs. 23, 24, 25 and 26.

Land rough, mountainous. Soil poor.

Dense fir and cedar timber.

Thick undergrowth of hazel, 80.75 chs.

North on random line bet. secs. 23 and 24.

Va. 20*E.

40.00 Set temp $\frac{1}{4}$ sec. cor.

79.56 Intersect E and W line, 40 lks. West of cor. to secs. 13, 14, 23 and 24, which is a post, 4 ins. diam., in ground marked T 22 S S 13 on NE., R 4 W S 24 on SE., S 23 on SW., S 14 on NW face from which

A Cedar, 18 ins. diam., bears N.55*W., 36 lks. dist., marked T 22 S R 4 W S 13 B T.

A Cedar, 30 ins. diam., bears S.67*W., 38 lks. dist., marked T 22 S R 4 W S 24 B T.

A Cedar, 20 ins. diam., bears S.8*E., 66 lks. dist., marked T 22 S R 4 W S 23 B T.

A Cedar, 8 ins. diam., bears N.88*E., 37 lks. dist., marked T 22 S R 4 W S 14 B T.