

Subdivisions of T 22 S., R 4 W., W.M.

CHAINS

39.60 Set post, 4 ins. diam., 4 ft. long, 12 ins. in ground for
qr. sec. cor., marked $\frac{1}{2}$ S on N face, from which
A Fir, 48 ins. diam., bears S.45*E., 2 lks. dist.,
marked $\frac{1}{2}$ S B T.
A Fir, 36 ins. diam., bears N.65*W., 53 lks. dist.,
marked $\frac{1}{2}$ S B T.

79.20 The cor to sec. 13, 14, 23 and 24.

Land mountainous, soil 2nd rate.

Timber fir and cedar.

Thick undergrowth of hazel, 79.20 chs.

Survey ended Oct. 27, 1884.

GENERAL DESCRIPTION:

The portion of this township that the foregoing field notes describe is exceedingly rough, being most all the way in and over the Calipooya mountains, there are settlers scattered all through the different sections but the lines did not cross their improvements. Grass grows in all places where the sun can get at the ground. Timber fir and cedar. Soil thin but I understand on some of the streams there are quite large spots of good available land.

Subdivisions of T 22 S., R 4 W., W.M. as surveyed by Oscar F. Thiel, U.S. Deputy Surveyor under his Special Instructions, dated August 15, 1901.

*SEE ALSO
C.S. 61/5*
The cor. of secs. 26, 27, 34 and 35, having disappeared, I re-establish it by setting a Cedar post, 3 ft. long, 4 ins. sq., 24 ins. in the ground for cor. of secs. 26, 27, 34 and 35, marked T 22 S S 26 on NE., R 4 W S 35 on SE., S 34 on SW and S 27 on NW faces, with 1 notch on S and 2 notches on E faces, from which