

Resurvey of 5th Standard Parallel S., through Rs. 6 & 7 W.

CHAINS

A Fir, 6 ins. diam., bears S.54*E., 59 lks. dist.

mkd. T 23 S R 6 W S 6 B T.

A Chincapin, 5 ins. diam., bears S.52*W., 36 lks. dist.

mkd. T 23 S R 7 W S¹ B T.

This cor. is on the southerly slope of spur, 100 ft. below top.

Note. - Since the 5th Standard Parallel South through Tps. 23 S., Rs. 6 and 7 W., was originally established as a base from which to project surveys Southward, I re-established the standard cors. above described to refer to the secs. on the South for the purpose of preserving the uniformity of the corners throughout the line.

Land, mountainous.

Soil, 1st, 2nd and 3rd rate.

Timber, Fir, Maple, Hemlock, Cedar, Chincapin, Yew and Alder.

Dense undergrowth of Hazel, Vine maple, Thimble-berry, Mountain balm, Willow, Salmon-berry, Fir and Hemlock.

Land, mountainous, heavily timbered or covered with dense undergrowth. 80.47 chs.

Thence

N.89*54'W., on a true line along the S. Bdy. of sec. 36,

T. 22 S., R 7 W.

Descend.

11.95 Wagon road, bears NW. and SE., 75 ft. below standard Tp. cor.

12.47 Creek, 12 lks. wide, course N.20*W., 25 ft. below road; foot of descent.

13.60 Fence, bears NW. and SE; thence across grain field.

18.90 Creek, 2 lks. wide, course NE.

19.00 Fence, bears NW and SE;

Ascend spur.