

Retracing of 5th Standard line on N. Bdy. of T. 23 S., R. 7W.

CHAINS	<p>Fir tree, 10 ins. diam., bears N.89*W., 10 lks. dist.</p> <p>80.00 Marked a Fir, 8 ins. diam., for the Cor. to Secs. 1 and 2, from which a</p> <p>Maple tree, 6 ins. diam., bears S.67*E., 32 lks. dist.</p> <p>Fir tree, 8 ins. diam., bears S.68*W., 22 lks. dist.</p> <p>Land, broken, mountainous, 2nd and 3rd rate.</p> <p>Timber, chiefly burned. February 13, 1881.</p>
	Va.19*E.
	Running West on North Bdy. of Sec. 2..
5.00	Top of ridge, course NW.
10.00	Enter prairie, course N. and S.
30.00	Leave same, course N. and S.
36.50	Qr. sec. cor., witness trees all standing viz:
	Fir tree, 40 ins. diam., bears S.45*E., 57 lks. dist.
	Fir tree, 5 ins. diam., bears S.67*W., 31 lks. dist.
	Set new cor. post as per instructions.
64.80	Creek, 5 lks. wide, course SW.
76.50	Old cor., bearing trees standing, set new post as per instructions, from which a
	Fir, tree, 24 ins. diam., bears S.15*W., 10 lks. dist.
	Dogwood, 4 ins. diam., bears S.50*E., 30 lks. dist.
	Land, mountainous; soil, 2nd rate.
	Scattering Fir, Cedar, Oak, and Laurel trees.
	Feb. 13, 1881.
	Subdivisions of T. 22 S., R. 7 W., W. M., as surveyed by Carl S. Nicklin, Deputy Surveyor, under joint contract No. 664, dated May 23, 1896.
	From the standard cor. of secs. 35 and 36, T. 22 S., R. 7 W., which I established Nov. 24, 1897, I run N.0*1'W., on a true line bet. Secs. 35 and 36.
	Mag. Decl. 20*30'E.
	Descend.
8.21	Creek, 2 lks. wide, course NE., 250 ft. below standard Cor.
	Ascend spur.