

Meanders, T. 22 S., R. 8 W.

CHAINS

<u>Course</u>	<u>Chains</u>	
S.53*W.	15.00	
S.44*W.	23.00	
S.46 $\frac{1}{2}$ *W.	14.00	
S.50 $\frac{1}{2}$ *W.	7.50	To meander post bet. Secs. 7 & 18. Thence in Sec. 18.
S.48 $\frac{1}{2}$ *W.	20.00	
S.47 $\frac{1}{2}$ *W.	15.00	
S.45*W.	14.70	To meander post on West Bdy. of T.

General Description

The surveyed portion of this Township is hilly & mountainous. Soil, 1st & 2nd rate.

The valley of the Umpqua is generally hilly prairie & mostly taken by settlers.

Timber, fir & oak.

Undergrowth, vine maple, hazel & oak.

Portion of West Bdy. of T. 22 S., R. 8 W.
As surveyed by W. H. Byars, Deputy Surveyor, Under
Contract No. 202, dated March 11, 1874.

Begin at meander post on Tp. line bet. Secs. 13 & 18,
T. 22 S., Rs. 8 & 9 W. $\frac{1}{4}$ cor. 5.60 S. of river.
North, across river.

Var. 18*45'E.

Across to north bank. Then set instrument West of line.
Thence M. post South of river bears S.24 $\frac{1}{2}$ *E. A flag
on line North of river bears N.24 $\frac{1}{2}$ *E. Then measure
distance.

14.60 Across river. Set M. Post-- A W. Oak post, 5 ins. diam.,
40 ins. long, 18 ins. in ground from which
An alder, 10 ins. diam., bears N.60*E. Dist. 80 lks.
A W. oak, 6 ins. diam., bears S.45*W. Dist. 79 lks.

14.85 Enter grain field, course of river.