

## Resurvey of the West Bdy. of T. 22 S., R. 8 W.

CHAINS		
	North, bet. Secs. 1 and 6.	
		Var. 20°E.
	Ascend.	
6.50	Top of ridge, course NW. and SE.	+150
	Descend.	
16.75	Creek, 2 lks. wide, course SE.	-200
	Ascend.	
25.50	Top of ridge, course E. and W.	+250
	Descend.	
36.50	Creek, 5 lks. wide, course E.	-100
	Ascend.	
39.41	The $\frac{1}{4}$ sec. cor. As the old post was badly decayed, Set fir post, $4\frac{1}{2}$ ft. long, 4 ins. sq., 24 ins. in the ground on steep hillside sloping South, marked $\frac{1}{4}$ S on the West face, from which A maple, 14 ins. diam., bears N.70°E. 20 lks. dist. marks grown over. A fir, 10 ins. diam., bears N.55°W. 46 lks. dist. marks grown over.	
45.00	Top of ridge, E. and W.	+150
	Descend.	
53.75	Creek, 2 lks. wide, course NE.	-75
	Pass over spur.	
59.90	Creek, 3 lks. wide, course East.	
	Ascend.	
73.00	Top of ridge, course E. and W.	+250
	Descend.	
77.93	To a point 83 lks. West of the Cor. to Tps. 21 and 22 S., Rgs. 8 and 9 W. which is a post 2 ft. above ground, $4\frac{1}{2}$ ins. sq., firmly set, marked T 21 S S 31 on the NE., R 8 W S 6 on the SE., T 22 S S 1 on the SW. and R 9 W S 36 on the NW. faces with 6 notches on the N., S., E. and W. edges, from which	