

County Surveyor's Record, Douglas County, Oregon

Subdivisions and Meanders of T. 22 S., R. 9 W.

CHAINS North, between secs. 8 and 9.

20.00 Enter timber.

27.00 Set post, from which,
 A Fir, 12 ins. diam., bears S.8*E., 35 lks. dist.
 A Fir, 20 ins. diam., bears S.23*W., 35 lks. dist.
 It is impracticable to run the above lines further on
 account of the roughness of the ground.

West, between secs. 8 and 17.

11.10 Fence.

11.50 Road to Scottsburg.

12.00 Fence and Goldin's house, bears N., 310 lks, dist.

24.84 Set meander post, on right bank of Umpqua, from which,
 A Willow, 5 ins. diam., bears N.55*W., 21 lks, dist.
 Raised mound, as per instructions.

Meanders of T. 22 S., R. 9 W.

Meanders in sec. 17, commencing at post between 16 and 17.
 thence on right bank down stream.

Courses	Chains
N.55½*W.	8.50 ✓
N.50*W.	9.00
N.36½*W.	8.80
N.31½*W.	5.00
N.8½*W.	11.00
N.9*W.	10.00 to meander post between secs. 8 and 17.

Meanders in sec. 8, commencing at post between secs. 8
 and 17, thence on right bank down stream.

Courses	Chains
N.4*E.	25.06 ✓
N.11*W.	9.00 ✓