

County Surveyor's Record, Douglas County, Oregon

Subdivisions of Fractional T. 22 S., R. 9 W.

CHAINS		
	South, 89°53'W., on true line.	
25.00	Hancock's house, bears N.34°W. about 5 chs. Enter valley, Course N. and S.	- 600
27.50	Read, Course N. and S.	
36.00	A creek, 75 lks. wide, Course S.	
40.11	Set a Fir post, 40 ins. long, 5 ins. diam., 20 ins. in ground, for $\frac{1}{2}$ sec. post, from which, A Fir, 5 ins. diam., bears S.5°W., 58 lks. dist. A Fir, 30 ins. diam., bears N.30°W., 114 lks. dist. Begin ascent. Leave valley, Course N. and S.	
65.00	Top of spur, Course SE.	+ 100
80.22	To sec. corner. Land, broken, second rate. Timber, some scant. Brush, Fir, Oak, Alder and Hazel. November 3, 1874.	
	North, between secs. 10 and 11. Va. 20°E.	
8.50	Top of ridge, Course E. and W. Enter timber.	+ 200
19.75	A creek, 1 lk. wide, Course W.	
21.75	A creek, 1 lk. wide, Course W.	
40.00	Set a Fir post, 3 feet long, 18 ins. in ground, 5 ins. diam., from which, A Fir, 50 ins. diam., bears S.68°E., 22 lks. dist. A Fir, 16 ins. diam., bears N.80°W., 79 lks. dist.	
49.25	A creek, 1 lk. wide, Course W.	Rolling
62.75	A creek, 2 lks. wide, Course W.	
80.00	Set a Fir post, 3 feet long, 16 ins. in ground, 4 ins. diam., for corner to secs. 2, 3, 10 and 11, from which, A Maple, 6 ins. diam., bears N.30°E., 78 lks. dist. A Fir, 60 ins. diam., bears S.50°E., 48 lks. dist. A Fir, 60 ins. diam., bears S.72°W., 75 lks. dist. A Dogwood, 5 ins. diam., bears N.25°W., 24 lks. dist. Land, broken, third rate. Timber, Fir, Hemlock, Cedar, and a few other varieties. Underbrush, Same.	