

Subdivisions of Fractional T. 22 S., R. 9 W.

CHAINS

Timber, principally young Fir, good.  
 Underbrush, same, vine-Maple and mountain laurel.  
 November 10, 1874.

General Description

The land surveyed North of the river is principally valuable for the timbers thereon. Other portions would have been surveyed, but the incessant fogs or rains prevalent at this time of the year prevented the completion of the work. That South of the river was executed in the storm, at great disadvantage, for the accomodation of Mr. G. McCaha, who claims a pre-emption privilege in secs. 18 and 19. These lands also are only valuable for the timbers thereon.

Exterior and Subdivision Lines of T. 22 S., R. 9 W.  
 Same Deputy and Contract.

Beginning at the  $\frac{1}{4}$  sec. corner, between secs. 18, T. 22 S., R. 8 W., and 13, T. 22 S., R. 9 W. One witness tree standing.

South, on true line.

Va. 19\*E.

4.00	Begin ascent.	
13.50	Top of spur, Course W.	+ 400
31.50	A creek, 5 lks. wide, Course NW.	00
32.00	Steep ascent,	
40.00	Set post for corner to secs. 13, 18, 19 and 24, from which,	+ 500
	A Fir, 10 ins. diam., bears N.73*E., 87 lks. dist.	
	A Fir, 8 ins. diam., bears S.75*E., 63 lks. dist.	
	A Fir, 60 ins. diam., bears S.21*W., 35 lks. dist.	
	A Fir, 36 ins. diam., bears N.16*W., 63 lks. dist.	