

## Exterior and Subdivision Lines of T. 22 S., R. 9 W.

CHAINS		
	<p>Land, broken, second rate.            Timber, Fir.            Underbrush, same, and Willow and vine-Maple along river.            August 26 1874.</p>	
	<p>Beginning at corner to secs 13 and 24, East boundary            and South on true line.            Va. 19°E.</p>	
27.00	Broken, sloping, East top of ridge, Course E. and W.	+ 200
40.00	<p>Set a post for <math>\frac{1}{4}</math> sec. corner, a Dogwood, 4 feet long, 5            ins. diam., 18 ins. in ground, from which,            A Fir, 10 ins. diam., bears N.10°E., 22 lks. dist.            A Fir, 10 ins. diam., bears S.65°W., 18 lks. dist.</p>	
60.00	A creek, 1 lk. wide, Course S.10°W.	
80.00	<p>Set Fir post, 40 ins. long, 4 ins. diam., 20 ins. in            ground, for corner post to secs. 19, 25, 24 and 30,            from which,            A Fir, 8 ins. diam., bears N.23°E., 8 lks. dist.            A Fir, 6 ins. diam., bears S.76°E., 6 lks. dist.            A Fir, 10 ins. diam., bears S.19°W., 14 lks. dist.            A Fir, 10 ins. diam., bears N.64°W., 41 lks. dist.</p>	
	<p>Land, second rate.            Timber, principally Fir.            Underbrush, Hazel, Maple and Dogwood.</p>	
	<p>From corner to secs. 13, 14, 23 and 24.            South, on true line, between secs. 23 and 24.            Va. 19°E.</p>	
20.00	Enter valley, Course NE. and SW.	- 400
33.00	A creek, course NE., 25 lks. wide.	
40.00	<p>Set an Alder post, 40 ins. long, 5 ins. diam., for the <math>\frac{1}{4}</math>            sec. corner, from which,</p>	