

Exterior and Subdivision Lines of T. 22 S., R. 9 W.

CHAINS		
	A Maple, 5 ins. diam., bears N.25*E., 24 lks. dist.	
	An Alder, 8 ins. diam., bears S.15*W., 21 lks. dist.	
41.00	Intersect creek.	
42.50	Leave same.	
80.00	Set Maple post, 42 ins. long, 5 ins. diam., for corner.	-200
	to secs. 23, 24, 25, and 26, from which,	
	A Fir, 12 ins. diam., bears N.54*E., 67 lks. dist.	
	An Alder, 8 ins. diam., bears S.77*E., 25 lks. dist.	
	An Alder, 12 ins. diam., bears S.28*W., 60 lks. dist.	
	An Alder, 8 ins. diam., bears N.82*W., 37 lks. dist.	
	Land, North part, hilly, third rate; South part, rolling second rate.	
	Timber and underbrush, principally burned. Land covered with fern.	
	August 27, 1874.	
	East, on Random line, between secs. 24 and 25.	
	Va. 19*E.	
40.00	Set temporary $\frac{1}{2}$ sec. corner.	
80.22	Intersect East boundary, 30 lks. North of corner.	
	North, 89*47'W., on true line.	
2.50	A creek, 1 lk. wide, course S.	- 50
17.50	Top of ridge, Course S.	+ 200
22.00	A creek, 3 lks. wide, Course S.	- 500
35.75	A creek, 2 lks. wide, Course S.	
40.11	Marked a Fir, 24 ins. diam., for the $\frac{1}{2}$ sec. corner.	
	No trees near.	
60.25	A creek, 4 lks. wide, Course S.	
80.22	To sec. corner.	
	Land, hilly, second rate.	
	Timber, principally Fir, good.	
	Underbrush, same.	